

Update 1.2.35008, 1.2.35404 auf 1.3.37307

Updatedatei:

- eNetServer_1.3.37307.iuf

Geschätzte Updatedauer: 10 - 70 Minuten

i	Reihenfolge beim Update beachten: 1. Gira Control 9 Client zuerst auf die Version 1.4 updaten. 2. eNet Server dann auf die Version 1.3 updaten.
---	---

Achtung: Der eNet-Server darf während des Vorgangs nicht von der Stromversorgung getrennt werden! Das Update ist abgeschlossen, wenn die Power-LED am eNet-Server nicht mehr blinkt und die Login-Seite angezeigt wird.

Achtung: Bitte sichern Sie vor dem Update ihre vorhandenen Projekte, da diese durch einen Fehlschlag im Update nicht wieder hergestellt werden.

Bitte beachten: Das aktuelle Projekt wird während des Updates konvertiert. Das kann den Update-Prozess um bis zu einer Stunde verlängern, abhängig von der Projektgröße.

Änderungen:

- Unterstützung des Produktes Steinel SensIQ
 - Neuer Bewegungskanal, Funktionsweise für Aktoren R1.x
 - Neuer Schaltaktorkanal mit Impulsbetrieb
- Importfunktion für Konfigurationen mit bereits vorhandenem Namen
- Speicherung wichtiger Diagnoseinformationen am Projekt
- Beschleunigtes Laden von Projekten mit vielen Visu-Aktionen
- Darstellung der Szenenwerte in der Projektdokumentation
- Die Verbindung Client/Server ist jetzt ausschließlich mit TLS 1.1 / 1.2 verschlüsselt
- Anpassung an Windows 10/Edge
- Fehlermeldungen werden je nach Signifikanz farbig dargestellt
- Firmware-Updates folgender Geräte:
 - Steinel SensIQ
- div. Performanceverbesserungen
- Fehlerbehebungen
- Neuer Visualisierungs-Client

Versionen:

- Devices 1.5.12
- IBN-Client 6.7.0
- Middleware 2.0.10
- RootFS 1.1.1
- Servlet 6.7.0
- Visuclient 1.5.1

English

Update 1.2.35008, 1.2.35404 to 1.3.37307

Update file:

- eNetServer_1.3.37307.iuf

Estimated update duration: 10 - 70 minutes

	<ol style="list-style-type: none">1. Update first Gira Control 9 Client to version 1.4.2. Then upgrade eNet Server to version 1.3.
---	---

Attention: Don't disconnect the eNet-Server from power supply during the update action!
The update is done if the power LED of the DRA server doesn't blink anymore and the login site is shown.

Attention: Please backup your projects because projects won't be recovered due to possible update failures.

Please note: The active project will be converted during the update. Dependent on projects size this update may take up to one hour of progress.

Changes:

- Support of product Steinel SensIQ
 - New movement channel, function property in actors R1.x
 - New switching channel with pulse operating mode
- Import function of configurations with already available name
- Saving of important diagnostic information into project file
- Accelerated loading of projects with many visualisation actions
- Displaying of scene values in project documentation
- Client-server connections exclusively encrypted with TLS 1.1 / 1.2
- Addaption to Windows 10/Edge
- Colorized error messages depending on significance
- Firmware updates of following devices:
 - Steinel SensIQ
- Div. performance improvementsBugfixes
- New visualisation client

Versions:

- Devices 1.5.12
- IBN-Client 6.7.0
- Middleware 2.0.10
- RootFS 1.1.1
- Servlet 6.7.0
- Visuclient 1.5.1